Thursday, 8/23/2007 11:51:45 AM Date Kim Johnston **Process Sheet** : HARNESS ASSEMBLY **Drawing Name** : CU-DAR001 Dart Helicopters Services Customer Job Number : 34229 : 12997 **Estimate Number** : NA : D412702113A **Part Number** P.O. Number S.O. No. : N/A : ICA D412-702 P79 R3 : 8/23/2007 **Drawing Number** This Issue : N/A : NC Project Number Prsht Rev. : N/A : SMALL /MED FAB **Drawing Revision** Type First Issue NIA Material Previous Run **Due Date** : 9/3/2007 Qty: 4 Um: Each Written By Checked & Approved By EC : est rev A 07.08.22 new issue Comment **Additional Product** Job Number: Description: Machine Or Operation: Seq. #: DOCUMENT CONTROL 1.0 DC Comment: DOCUMENT CONTROL type labels per PPP D412-702-113A CHG001 BRACKET 2.0 D35702 Comment: Qty.: 1.0000 Each(s)/Unit Total: 4.0000 Each(s) **BRACKET** batch 3 1867 07-08-27 SHOULDER HARNESS RH 3.0 D3579044 Comment: Qty.: 1.0000 Each(s)/Unit Total: 4.0000 Each(s) 4.0 MS24694S50 Screw Comment: Qty.: 4.0000 Each(s)/Unit Total: 16.0000 Each(s) Screw batch: m04625 mr 07-08-27 5.0 AN960JD10L Washer Comment: Qty.: 4.0000 Each(s)/Unit Total: 16.0000 Each(s) Washer batch: M103044 MF 07-08-27

į

Dart Aerospace Ltd

W/O:		WORK ORDER CHA	ANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Dart No.		DAD # . Foult Cotonomi	NOD. V.				

Part No:	PAR #:	_ Fault Category:	NCR: Ye	s No	DQA:	_ Date: _	
			QA	N/C	Closed:	_ Date: _	

NCR:			WORK ORD	ER NON-CONFORMANO	E (NCR)					
DATE		Description of NC		Corrective Action Section B		Verification	Approval Chief Eng	Approval QC Inspector		
	STEP	Section A Init	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C				

	1 ,									

NOTE: Date & initial all entries

Date: Thursday, 8/23/2007 11:51:45 AM Kim Johnston User: **Process Sheet** Drawing Name: HARNESS ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Job Number: 34229 Part Number: D412702113A Job Number: Description: Seq. #: Machine Or Operation: Nut MS21042L3 6.0 16.0000 Each(s) Comment: Qty.: Total: 4.0000 Each(s)/Unit Nut batch: M104931 SMALL & MEDIUM FAB RESOURCE 1 SMALL FAB 7.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 Assemble as per dwg ICA D412-702 p.79 INSPECT WORK TO CURRENT STEP 8.0 QC5 Comment: INSPECT WORK TO CURRENT STEP PACKAGING RESOURCE #1 9.0 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-702-113A CHG001 Location: PPP Rev. FINAL INSPECTION/W/O RELEASE 10.0 QC21 Comment: FINAL INSPECTION/W/O RELEASE N 27.08.28 Job Completion

Dart Aerospace Ltd


W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
04:08:2Y	7.0-	Pick Ix 035\$A-2 label B <u>12085</u> . 34 marine adhesive 5200 m 104524 Bond the label to the buckle as per Duy 03579, and QSI 015	mr	27	4	PAUSTY	120824			

Part No:	PAR #:	_ Fault Category:	NCR: Yes No	DQA:	Date: <u>07/08/08</u>
			QA: N/C C	losed:	Date:


NCR:			WORK ORD	ER NON-CONFORMANC	E (NCR)			
		Description of NC		Corrective Action Section B		Verification		A
DATE	E STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		Approval QC Inspector
		<i>:</i>						
			·					
· -								
	<u> </u>							1

NOTE: Date & initial all entries

ICA Page 79 (80 blank) of 98



DETAIL 'K' D412-702-101A/-103A/-105A/-107A/-109A/-115A/-117A AND D412-702-101BI-103BI-105BI-107BI-109BI-115BI-117B HARNESS ASSEMBLIES (BELTS, K6.2 CLIP AND D3569-1/-2/-3 DECAL NOT SHOWN)



DETAIL 'L' D412-702-111AI-111BI-113AI-113B HARNESS ASSEMBLIES UNCONTROLLED COPY (BELTS AND D3569-1/-2/-3 DECALS NOT SHOWN)

RETURN TO **ENGINEERING**

SHOP COPY

WITHOUT NOTICE

WORK, ORDER

• COPYRIGHT © 2004 BY DART AEROSPACE LTD. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

25-00-00

Page 49 (50 blank) of 68